

Assemble Guide

server rack

Assemble the frame with the bottom plate.
Use HEX SOCKET CAP SCREWS:
M8*12 and Hex Flange Nut)




Warning: Make sure that the frame's side with the rectangle holes is on the external side.



Assemble the frame with the top plate by using the same screws as above (step 1).




Assemble the leveling feet and the castors (using the following screws: M6*M12).



Assemble the cable entry cover. Use the self tapping screw: M3.5*6



Assemble the horizontal rail. Use screws: M6*M12 and catch nut.



Warning: Don't put the horizontal rail exactly in the middle of the high. This space needs to remain free.



Assemble the 4 mounting angles. Use screws: M6*M12 and catch nut.



Assemble the front and the rear door with the door locks.



Screw the 4 little metal pieces on each side of the rack by using the screws: M3.5*6. Then assemble the side panels.

